	<b>Service NOTIFICATION</b>	
	<b>Flight Design GmbH</b> Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99 E-Mail: <a href="mailto:info@flightdesign.com">info@flightdesign.com</a>	<b>SN-SECS-CT2k-03;          Revision 0</b>
		Date of Initial Publication: <b>15-Oct-2008</b> Publication Date of this Revision: <b>15-Oct-2008</b>

# Service NOTIFICATION

## Coolant hose cracking

SN-SECS-CT2k-03

### 1 Planning Information

#### 1.1 Affected Aircraft

Type: CT  
 Model: CT2k  
 Serial Number: All serial numbers  
 Applicable Countries: All Countries where BCAR Section S standards are in effect

#### 1.2 Concurrent Documents

None

#### 1.3 Reason

Re- issue of existing document in order to implement it to the new Service document numbering system

#### 1.4 Subject

All information see paragraph 3

#### 1.5 Compliance

All information see paragraph 3

#### 1.6 Personnel Qualifications

All information see paragraph 3

#### 1.7 Approval


All information see paragraph 3

#### 1.8 Weight and Center of Gravity

All information see paragraph 3

#### 1.9 References

All information see paragraph 3

	<b>Service NOTIFICATION</b>	
	<b>Flight Design GmbH</b> Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99 E-Mail: <a href="mailto:info@flightdesign.com">info@flightdesign.com</a>	<b>SN-SECS-CT2k-03;          Revision 0</b>
		Date of Initial Publication: <b>15-Oct-2008</b> Publication Date of this Revision: <b>15-Oct-2008</b>

### 1.10 Superseded Documents

Technical Advice No. 3

Safety Directive No. 3

### 1.11 Contact Details

For further information or to report any Safety of Flight or Service Difficulty issues contact your Distributor responsible for your country.

Specific contact in USA:

Flight Design USA

P.O. Box 325 South Woodstock, CT 06267

Tel: 860 963 7272 / Fax: 860 963 7152

Web: [www.flightdesignUSA.com](http://www.flightdesignUSA.com)

E-Mail: [airworthiness@flightdesignUSA.com](mailto:airworthiness@flightdesignUSA.com)

For all other countries and in cases where the local distributor is not known or available contact Flight Design GmbH directly.

## 2 Resources

### 2.1 Materials

All information see paragraph 3

### 2.2 Manpower


All information see paragraph 3

### 2.3 Cost

All information see paragraph 3

## 3 Instructions

The following is the 1:1 copy of the existing document following the old numbering system.

	<b>Service NOTIFICATION</b>	
	<b>Flight Design GmbH</b> Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99 E-Mail: <a href="mailto:info@flightdesign.com">info@flightdesign.com</a>	<b>SN-SECS-CT2k-03;          Revision 0</b>
		Date of Initial Publication: <b>15-Oct-2008</b> Publication Date of this Revision: <b>15-Oct-2008</b>

**TECHNICAL ADVISE No. 3**

Date:

10.09.2002

**Subject:**


Rubber hoses

**Case:**

After supplier change in 2000, there has been reported rubber hoses, which show cracks on the outside of the hose.

**Advise:**

- Please exchange this rubber hoses. New rubber hoses for planes less than 2 years old are supplied for free, if old ones are send back to Flight Design for analyse.

	<b>Service NOTIFICATION</b>	
	<b>Flight Design GmbH</b> Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99 E-Mail: <a href="mailto:info@flightdesign.com">info@flightdesign.com</a>	<b>SN-SECS-CT2k-03;          Revision 0</b>
	Date of Initial Publication: <b>15-Oct-2008</b> Publication Date of this Revision: <b>15-Oct-2008</b>	

## 4 Appendix

### 4.1 Changes to Previous Revision

No content changes – re-issue of existing document to new numbering system

### 4.2 Feedback Template Flight Design

All information see paragraph 3