

#### Flight Design GmbH

Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

### SN-ASTM-CT2k-03; Revision 0

Date of Initial Publication: **15-Oct-2008**Publication Date of this Revision: **15-Oct-2008** 

# **Service NOTIFICATION**

# **Coolant hose cracking**

#### SN-ASTM-CT2k-03

### 1 Planning Information

### 1.1 Affected Aircraft

Type: CT

Model: CT2k

Serial Number: All serial numbers

Applicable Countries: All Countries where ASTM standards are in effect

#### 1.2 Concurrent Documents

None

#### 1.3 Reason

Re- issue of existing document in order to implement it to the new Service document numbering system

#### 1.4 Subject

All information see paragraph 3

#### 1.5 **Compliance**

All information see paragraph 3

#### 1.6 Personnel Qualifications

All information see paragraph 3

#### 1.7 Approval

All information see paragraph 3

#### 1.8 Weight and Center of Gravity

All information see paragraph 3

#### 1.9 References

All information see paragraph 3



#### Flight Design GmbH

Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

#### SN-ASTM-CT2k-03; Revision 0

Date of Initial Publication: **15-Oct-2008**Publication Date of this Revision: **15-Oct-2008** 

#### 1.10 **Superseded Documents**

Technical Advice No. 3

Safety Directive No. 3

#### 1.11 Contact Details

For further information or to report any Safety of Flight or Service Difficulty issues contact your Distributor responsible for your country.

Specific contact in USA:

Flight Design USA

P.O. Box 325 South Woodstock, CT 06267 Tel: 860 963 7272 / Fax: 860 963 7152

Web: www.flightdesignUSA.com

E-Mail: airworthiness@flightdesignUSA.com

For all other countries and in cases where the local distributor is not known or available contact Flight Design GmbH directly.

#### 2 Resources

#### 2.1 Materials

All information see paragraph 3

#### 2.2 Manpower

All information see paragraph 3

#### 2.3 <u>Cost</u>

All information see paragraph 3

#### 3 Instructions

The following is the 1:1 copy of the existing document following the old numbering system.



#### Flight Design GmbH

Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

#### SN-ASTM-CT2k-03; Revision 0

Date of Initial Publication: **15-Oct-2008**Publication Date of this Revision: **15-Oct-2008** 

# FLIGHT DESIGN USA SAFETY DIRECTIVE No.3

# Coolant hose cracking

# <u>Notification</u>

#### Flight Design USA

Woodstock Airport 91, Route 169, PO. Box 325 South Woodstock, Ct. 06267 Tel: 860-963-7272 Fax: 860-963-7152 fstar@rcn.com

Pages: One (1)Original Issue

Date Issued: October 6, 2006

Scope: CT2Ks up, to but not including, serial No. 01-04-01-12

#### Discussion

Following a change in supplier in 2000, some engine hoses were found to develop surface cracks. Flight Design Technical Advise No.3 was issued requiring that engine hoses be checked and replaced as needed.

<u>Note:</u> This event and subsequent corrective action, Flight Design Technical Advise No. 3, upon which this Safety Directive is based, predated the importation and registration of Flight Design aircraft into the U.S.

#### Corrective Action

No action required at the time of issuance.

#### Reminder

Flight Design reminds the Owner/Operator of a Flight Design aircraft that compliance with all Safety Directives, Aircraft Operating Instructions, Maintenance Manuals as well as the reporting of any and all Safety of Flight or Service Difficulties by the Owner/Operator is *mandatory* for the operation of an S-LSA aircraft.

FDUSA SD3 Page 1 of 1



#### Flight Design GmbH Sielminger Str. 65

Sielminger Str. 65 D-70771 L.-Echterdingen Tel +49 (0)711 90287-0 Fax +49 (0)711 90287-99

E-Mail: info@flightdesign.com

### SN-ASTM-CT2k-03; Revision 0

Date of Initial Publication: **15-Oct-2008**Publication Date of this Revision: **15-Oct-2008** 

# 4 Appendix

## 4.1 Changes to Previous Revision

No content changes - re-issue of existing document to new numbering system

### 4.2 Feedback Template Flight Design

All information see paragraph 3