Safety Alerts	Dett	Carl i and	A.C	0 1	
Download	Date	Subject		Compliance	Manual
SA-SECS-CTSW- 06	07-03-2013	Inspection for applicability of Rotax ASB-912-062UL R1 / ASB-914-044UL R1, ASB-912- 062R1 / ASB-914-044R1.	All above listed CT type aircraft models with aircraft serial number earlier than x 12 05 02 (excluded, with (x) being the identifier of the relevant model, when applicable), where in addition the engine has been exchanged on aircraft after delivery of the aircraft from the factory.	before the next flight	n/a
SA-SECS-CTSW- 05	30-05-2012	Inspection for applicability of Rotax ASB-912-061 / ASB-912- 061UL	All CTSW up to S/N 11- 07-08	before the next flight	n/a
SA-SECS-CTSW- 04	28-11-2011	Checking of the Crankshaft Journal for ROTAX Engine Type 912 and 914	All S/N up to S/N D-11- 07-08 (inclusive)	before next flight, but at latest before 01 January 2012	n/a
SA-SECS-CTSW- 01	15-10-2008	Engine Mount Bolts	all s/n up to 05-05-01	in the next 20 hours	n/a
SA-SECS-CTSW- 02	15-10-2008	Servo Tab Spring	CTSW 2006 from 05-11- 09 to 06-09-05		Maintenance Manual
SA-SECS-CTSW- 03	15-10-2008	Trim Tab Reinforcement	CTSW 2006 model year 2006 and 2007 s/n from 06-07-15 to 07-05-18 (incl.) when equipped with full span trim tab (assembled before September 1st 2007)	before the next flight	070625 Trim Tab Reinforcemen Procedure; Maintenance Manual
Service Bulletins				·	
Download	Date	Subject	Affected	Compliance	Manual
SB-LTUL-CTSW- 99 SB-SECS- CTSW-99	03-02-2021	Equipment Manufacturer Notification	n/a	<b>n</b> /o	at each annual inspection
SB-LTUL-CTSW- 13 SB-SECS- CTSW-08	02-10-2015	Verification of Rescue System Cover Installation.	up to serial number D-11- 07-08 (including)	latest within 3 months following the issue date of this Notification, or at the next annual inspection of the aircraft, whichever comes first.	n/a
SB-LTUL-CTSW- 14 SB-SECS- CTSW-09	02-10-2015	Inspection Horizontal Tail.	Aircraft S/N that have a horizontal tail produced of Aramid fabric installed	each 100 hrs inspection	n/a
SB-SECS-CTSW- 06	08-10-2010	Garmin SL30 and SL40 Comm Radio Spurious Emissions Correction	All aircraft with Garmin SL30 Garmin SL40 units installed and with aircraft production date earlier than August 2010 (excluded), or when retrofitted with named Garmin units that have been produced by Garmin prior to October 2010 (excluded)	mandatory, but without time limit	n/a

SB-SECS-CTSW- 04	06-05-2010	Fuel Filter Exchange	All serial numbers prior to D-09-02-10 (usage of letters at beginning of S/N started in 2008, therefore all S/N beginning without a letter are affected)	before the next flight	CT Parts and Maintenance Manual CT Aircraft Maintenance Manual					
SB-SECS-CTSW- 05	30-11-2009	Stabilizer rear wall stiffening	weights but do not have pre-formed stiffeners supporting each individual trim tab hinge	where the next annual	CTSW Parts Catalog					
SB-SECS-CTSW- 01	15-10-2008	Radiator Isolator Mounts	all s/n from 03-04-03-16 to 05-06-03	before the next flight	Maintenance and Inspection Procedures Manual					
SB-SECS-CTSW- 02	15-10-2008	Landing Gear Inspection	all s/n	every 300 hours, at the annual inspection, or after a hard landing, whichever occurs first.	Maintenance and Inspection Procedures Manual					
Service Notification	Service Notifications									
Download	Date	Subject	Affected	Compliance	Manual					
SN-SECS-CTSW- 06	13-04-2016	Spare Parts Availability	not limited	n/a	n/a					
SN-SECS-CTSW- 01	15-10-2008	Rohaceall ® foam core	all s/n	n/a	n/a					
SN-SECS-CTSW- 02	15-10-2008	Engine coolant	all s/n	n/a	n/a					
SN-SECS-CTSW- 03	15-10-2008	Upper rudder hinge	all s/n	n/a	n/a					
SN-SECS-CTSW- 04	15-10-2008	Maintenance Inspection Intervals	all s/n	n/a	Maintenance and Inspection Procedures Manual; Rotax Maintenance Manual					
SN-SECS-CTSW- 05	22-09-2008	Information on Usage of Ethanol Blended Fuel	all s/n	n/a	Aircraft Operation Instructions; Rotax engine Operators Manual					