Safety Alerts					
	Date	Subject	Affected	Compliance	Manual
SA-LTUL-CT2k- 05	07-03-2013	Inspection for applicability of Rotax ASB-912-062UL R1 / ASB-914-044UL R1, ASB-912-062R1 / ASB-914-044R1.	aircraft serial number earlier than x 12 05-02 (excluded, with (x) being the identifier of the relevant model, when applicable), where in addition the engine has been exchanged on aircraft after delivery of the aircraft from the factory	before the next flight	n/a
SA-LTUL-CT2k- 04	30-05-2012	Inspection for applicability of Rotax ASB-912-061 / ASB-912-061UL.	all s/n	before the next flight	n/a
SA-LTUL-CT2k- 03	28-11-2011	Checking of the Crankshaft Journal for ROTAX Engine Type 912 and 914.	all s/n	before the next flight, but at latest before 01 January 2012	n/a
SA-LTUL-CT2k- 02	15-10-2008	Engine Mount Bolts	up to 05-05-01 (incl.)	n/a	Maintenance and Inspection Procedures Manual
01	15-10-2008	Securing of control system bolts	all s/n	before the next flight	n/a
Service Bulletins					1
Download	Date	Subject	Affected	Compliance	Manual
SB-LTUL-CT2k- 06	28-03-2014	Airspeed Markings	all s/n	latest at the next annual inspection	Flight and Maintenance Manual
SB-LTUL-CT2k- 05	08-10-2010		All aircraft with Garmin SL30 Garmin SL40 units installed and with aircraft production date earlier than August 2010 (excluded), or when retrofitted with named Garmin units that have been produced by Garmin prior to October 2010 (excluded)	mandatory, but without time limit	n/a
SB-LTUL-CT2k- 04	06-05-2010	Fuel Filter Exchange	All serial numbers prior to D-09-02-10 or F-09-02-01 (usage of letters at beginning of S/N started in 2008, therefore all S/N beginning without a letter are affected)	hafara tha navt flight	CT Parts and Maintenance Manual, CT Aircraft Maintenance Manual
SB-LTUL-CT2k- 01	15-10-2008	Radiator Isolator Mounts	from 03-04-03-16 to 05- 06-03	before the next flight	Maintenance and Inspection Procedures Manual
SB-LTUL-CT2k- 02	15-10-2008	Landing Gear Inspection	all s/n	n/a	Maintenance and Inspection Procedures Manual
					,

Download	Date	Subject	Affected	Compliance	Manual
SN-LTUL-CT2k- 12	13-04-2016	Spare Parts Availability	not limited	n/a	Flight and Maintenance Manual
SN-LTUL-CT2k- 06	19-12-2009	CT and CT2k MTOW increase for German Certification	all s/n	n/a	n/a
SN-LTUL-CT2k- 01	15-10-2008	Rohacell® foam core	all s/n	n/a	n/a
SN-LTUL-CT2k- 02	15-10-2008	Engine coolant	all s/n	n/a	n/a
SN-LTUL-CT2k- 04	15-10-2008	Coolant hose chafing	all s/n	n/a	n/a
SN-LTUL-CT2k- 03	15-10-2008	Coolant hose cracking	all s/n	n/a	n/a
SN-LTUL-CT2k- 05	15-10-2008	Upper rudder hinge	all s/n	n/a	n/a
SN-LTUL-CT2k- 09	15-10-2008	Aileron Bracket	up to 04-04-01	n/a	n/a
SN-LTUL-CT2k- 10	15-10-2008	Maintenance Inspection Intervals	all s/n	n/a	Maintenance and Inspection Procedures Manual, Rotax engine Maintenance Manual
SN-LTUL-CT2k- 07	15-10-2008	Recovery System Shoot Out Opening Check	all s/n	n/a	n/a
SN-LTUL-CT2k- 08	15-10-2008	Detection of Damages from Hard Landings	all s/n	n/a	n/a
SN-LTUL-CT2k- 11	22-09-2008	Information on Usage of Ethanol Blended Fuel	all s/n	n/a	n/a